

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Fig. 1 Prior Art






Fig. 2




Fig. 3A




Fig. 3B




FIG. 4A

Use of the alignment pattern




FIG. 4B

Blending of the overlap area




FIG. 4C




FIG. 4D - Reconstructed Image




FIG. 5A

Example of extraction of a
640x480 area out of the
1280x720 sensor array




FIG. 5B




FIG. 5C

Example of extraction of a 320x240
area out of the 1280x720 sensor
array and scaling the 320x240
section out to 640x480




FIG. 5D



FIG. 6A




FIG. 6B



FIG. 6C






FIG. 7








FIG. 9 De-Interlaced Active Frame




FIG. 10 Placement of the Tile Identifier Pattern in the Vertical Frame




FIG. 11A




FIG. 11B




FIG. 11C




FIG. 11D




FIG. 12




FIG. 13




FIG. 14